Assessment and Repair - External Corrosion Direct Assessment (ECDA)

12. ECDA Post-Assessment ((detail)	From the	review	of the	results	of s	elected	integrity	assessmen	nts, were
requirements met for post assessment?	' (AR.EC.	ECDAPOST	ASSESS	5.R) (d	etail)					

192.925(b)(4) (NACE SP-0502-2002 Section 6.2)

Sat+	Sat X	Concern	Unsat	N A	N C
------	----------	---------	-------	-----	-----

Notes - CIS was used DCVG, current mapper PCM, and depth on the first round. Second round was resistivity (4 pin). Camas was a pretty substantial coating anomalies. Single digit DCVG readings. 2011 magnitude 60 and 80 were dug. They were rock damages.

Assessment and Repair - Internal Corrosion Direct Assessment

10. Post-Assessment Evaluation and Monitoring (detail) From the review of the results of selected integrity assessments, did the operator assess the effectiveness of the ICDA process? (AR.IC.ICDAPOSTASSESS.R) (detail)

192.927(c)(4)(i) (192.927(c)(4)(ii))

Sat+	Sat X	Concern	Unsat	N A	N C
------	----------	---------	-------	-----	-----

Notes - For ICDA they identified critical angles of inclination. The history on the pipe shows no corrosion. At the Camas Gate they cut out a spool and determined there was no liquid and no oxidation.

Assessment and Repair - In-Line Inspection (Smart Pigs)

8. Validation of ILI Results (detail) From a review of field staff, do the employees and vendors validate ILI assessment results per their procedures? (AR.IL.ILIVALIDATE.O) (detail)

192.921(a)(1) (B31.8S Section 6.2.6)

Notes No ILI tools used

12. ILI Acceptance Criteria (detail) Do records indicate adequate implementation of the process for ILI survey acceptance? (AR.IL.ILIACCEPCRITERIA.R) (detail)

192.921(a) (B31.8S Section 6.2.5)

Sat+	Sat	Concern	Unsat	N A Y	N C
				X	

Notes No ILI tools used

15. Compliance with ILI Procedures (detail) Are O&M and IMP procedural requirements for the performance of ILI followed? (AR.IL.ILIIMPLEMENT.O) (detail)

192.620(d) Sat + Sat Concern Unsat X NC

Notes

No ILI tools used

Assessment and Repair - Other Technology

4. Other Technology (detail) From the review of the results of selected integrity assessments, was the assessment performed in accordance with the process and vendor recommendations? (AR.OT.OTPLAN.R) (detail)

N A 192.921(a)(4) Sat+ Sat Concern Unsat NC X Notes No other technology used

Assessment and Repair - Integrity Assessment Via Pressure Test

2. Pressure Test Results (detail) From the review of the results of pressure tests, do the test records validate the pressure test? (AR.PTI.PRESSTESTRESULT.R) (detail)

192.517(a) (192.505(a); 192.505(b); 192.505(c); 192.505(d); 192.505(e); 192.507(a); 192.507(b); 192.507(c); 192.617; 192.919(e); 192.921(a)(2); B31.8S Section 6.3.4)

ΝΔ Unsat Sat+ Sat Concern NC X

Notes Hydro or pressure testing was not used for IMP integrity assessment.

Assessment and Repair - Repair Criteria

9. Field Inspection - Remedial Actions (IM) (detail) Is anomaly remediation and documentation of remediation adequate for all covered segments? (AR.RC.REMEDIATION.O) (detail)

192.933(c) (192.933(a); 192.933(d))

Sat+

Sat X

Concern

NΑ

Unsat

NC

Notes

Looked at 4 digs in 2011. The operator recoated the affected areas and there were no cut-outs or metal loss.

Assessment and Repair - Repair Methods and Practices

2. Safety While Making Repair (detail) Are repairs made in a safe manner and to prevent damage to persons and property? (AR.RMP.SAFETY.O) (detail)

192.605(b)(9) (192.713(b))

Sat+

Sat X

Concern

Unsat

NC NΑ

Notes - The operator followed their safety procedures and there were no hot work permits or confined space.

5. Prevention of Accidental Ignition (detail) Perform observations of selected locations to verify that adequate steps have been taken by the operator to minimize the potential for accidental ignition. (AR.RMP.IGNITION.O) (detail)

192.751(a) (192.751(b); 192.751(c))

Sat+

Sat X

Concern Unsat NA X

N C

Notes - No blowdowns or hot work permits

17. Inspection of Welds (detail) Were welds inspected and examined in accordance with §192.241 and §192.243? (AR.RMP.WELDINSPECT.O) (detail) 192.241(a) (192.241(b); 192.241(c); 192.243(a); 192.243(b); Unsat NA Sat+ Sat Concern N C 192.243(c); 192.243(d); 192.243(e); 192.243(f)) X Notes - There was no construction performed to observe during this inspection 25. Transmission Lines Testing of Repairs (detail) Does the operator properly test replacement pipe and repairs made by welding on transmission lines? (AR.RMP.WELDTEST.O) (detail) NΑ 192.719(a) (192.719(b)) Sat+ Sat Concern Unsat NC X Notes - There was no construction performed to observe during this inspection Assessment and Repair - Stress Corrosion Cracking 4. Assessment Method (High pH SCC) (detail) From the review of the results of selected integrity assessments, did the operator perform an assessment using one of the methods specified in B31.8S Appendix A3? (AR.SCC.SCCDAMETHOD.R) (detail) NA 192.929(b)(2) (B31.8S Appendix A3) NC Sat+ Sat Concern Unsat X Notes - This line only meets one criteria for SCC out of the 5 for High pH SCC. **Design and Construction - Construction Welding Procedures** 3. Welding Procedures (detail) Are weld procedures being qualified in accordance with §192.225? (DC.WELDPROCEDURE.WELD.O) (detail) NΑ 192.225(a) (192.225(b)) Sat+ Sat Concern Unsat NC Notes - No construction or repair welding to observe **6. Welding Weather (detail)** Are welding operations are protected from certain weather conditions? (DC.WELDPROCEDURE.WELDWEATHER.O) (detail) N A 192.231 Sat+ Sat Concern Unsat N_C X Notes - No construction or repair welding to observe 11. Preparation for Welding (detail) Are welding preparations made in accordance with §192.235? (DC.WELDPROCEDURE.WELDPREP.O) (detail) NA 192.235 Sat Sat+ Concern Unsat N_C X Notes - No construction or repair welding to observe

Design and Construction - Construction Weld Inspection

3. Inspection and Test of Welds (detail) Are individuals who perform visual inspection of welding qualified? (DC.WELDINSP.WELDVISUALQUAL.O) (detail) NΑ Unsat 192.241(a) (192.241(b); 192.241(c); 192.807(b)) Sat+ Sat Concern NC X Notes - No construction or repair welding to observe 6. Nondestructive Test and Interpretation Procedures (detail) Are NDT procedures adequate? (DC.WELDINSP.WELDNDT.O) (detail) NΑ 192.243(a) (192.243(b)(1); 192.243(b)(2); 192.243(c); Sat+ Sat Concern Unsat NC 192.243(a)) X Notes - No NDT to observe 9. Repair or Removal of Weld Defects (detail) Are unacceptable welds removed and/or repaired? (DC.WELDINSP.WELDREPAIR.O) (detail) NΑ 192.245(a) (192.245(b); 192.245(c)) Sat+ Sat Concern Unsat NC X Notes - No construction or repair welding to observe **Design and Construction - Construction** 18. Inspection of Materials (detail) Are pipe lengths and other pipeline components visually inspected to ensure they are not damaged? (DC.CO.INSPECTVISUAL.O) (detail) NΑ 192.307 Sat+ Sat Concern Unsat NC X Notes - No construction to observe **21. Repair of Steel Pipe (detail)** Are repairs to steel pipe made in accordance with §192.309? (DC.CO.REPAIR.O) (detail) NΑ NC 192.309(a) (192.309(b); 192.309(c); 192.309(d); 192.309(e)) Sat+ Sat Concern Unsat X Notes - No construction or repairs to observe **34.** Installation of Pipe in a Ditch (detail) When pipe is placed in the ditch, is it installed so as to fit the ditch, minimize stresses, and protect the pipe coating from damage? (DC.CO.INSTALL.O) (detail) NΑ NC 192.319(a) (192.319(b)) Sat+ Sat Concern Unsat X Notes - No construction or repair welding to observe

Design and Construction - Pressure Testing

3. General - Testing Requirements (detail) Is pressure testing conducted in accordance with §192.503? (DC.PT.PRESSTEST.O) (detail) NΑ 192.503(a) (192.503(b); 192.503(c); 192.503(d)) Sat+ Sat Concern Unsat NC X Notes - No construction or testing to observe **6. Strength Test Requirements for SMYS > 30%. (detail)** *Is pressure testing conducted in accordance with* §192.505? (DC.PT.PRESSTESTHIGHSTRESS.O) (detail) NΑ 192.505(a) (192.505(b); 192.505(c); 192.505(d); 192.505(e)) Sat+ Sat Concern Unsat NC X **Notes** Notes - No construction or testing to observe **Design and Construction - Training and Qualification** 4. Skills and Knowledge of Personnel Performing Covered Tasks - Contractor employees (detail) Do selected contractor individuals performing covered tasks demonstrate adequate skills and knowledge? (DC.TQ.OQCONTRACTOR.O) (detail) Sat NΑ 192.805(b) (Operators OQ program manual) Sat+ Concern Unsat N C X Notes - NWN OQed indivuduals did the wrapping and coating. 6. Skills and Knowledge of Personnel Performing Covered Tasks - Operator Employee (detail) Do selected operator individuals performing covered tasks demonstrate adequate skills and knowledge? (DC.TQ.OQPLANEMPLOYEE.O) (detail) Sat 192.805(b) (Operators OQ program manual) Sat+ Concern Unsat N A N C X Notes - No construction or repairs to observe 8. Qualification of Personnel who Oversee and Perform Excavations and Backfilling Operations (detail) Do selected individuals who oversee marking, trenching and backfilling operations demonstrate adequate skills and knowledge? (DC.TQ.EXCAVATE.O) (detail) Sat 192.805(b) (ADB-06-01) Sat+ Concern Unsat N A N C X Notes - They were OQ qualified and were a company crew. 10. Qualification of Personnel Performing Hot Taps (detail) Do personnel performing hot taps demonstrate adequate skills and knowledge? (DC.TQ.HOTTAP.O) (detail) NA Sat+ Sat Unsat NC 192.805(b) (192.627) Concern X Notes - No construction or repairs to observe

Integrity Management - High Consequence Areas

8. IM High Consequence Areas - Identification Method 1 (Class Locations) (detail) Do records indicate adequate application of the §192.903 High Consequence Area definition (1) for the identification of HCAs? (IM.HC.HCAMETHOD1.R) (detail) Sat 192.903 (1)(i) (192.903(1)(ii); 192.903(1)(iii); 192.903(1)(iv)) Sat+ Concern Unsat NΑ NC X Notes -They took a conservative approach and used the UGA (Urban Growth Area) as a boundary. 10. IM High Consequence Areas - Identification Method 2 (Potential Impact Radius) (detail) Do records indicate adequate application of §192.903 High Consequence Area definition (2) for identification of HCAs? (IM.HC.HCAMETHOD2.R) (detail) NA Concern NC 192.903(2)(i) (192.903(2)(ii)) Sat+ Sat Unsat X Notes They do not use this method. **13. IM High Consequence Areas (detail)** Are HCAs correctly identified per up-to-date information? (IM.HC.HCADATA.O) (detail) Sat 192.905(c) Sat+ Concern Unsat NΑ NC X **Notes** They using the UGA as the HCA boundary - Class III **Integrity Management - Preventive and Mitigative Measures** 3. P&M Measures - Third Party Damage (detail) Does the preventive and mitigative process include requirements that threats due to third party damage be addressed? (Note: A subset of these enhancements are required for pipelines operating below 30% SMYS - See IM.PM.PMMTPDSMYS.P) (IM.PM.PMMTPD.P) (detail) Sat Unsat N C 192.917(e)(1) (192.935(b)(1); 192.935(e)) Sat+ Concern N A X Notes No unique threats for 3rd party. A farmer damaged the pipe in 2003. 12. P&M Measures - Automatic Shut-Off Valves or Remote Control Valves (detail) Has an adequate determination been made to determine if automatic shut-off valves or remote control valves represent an efficient means of adding

No specific project, but they are planning for any regulations that may be finalized.

Sat+

Sat

X

Concern

Unsat

NΑ

NC

protection to potentially affected high consequence areas? (IM.PM.PMMASORCV.R) (detail)

192.935(c)

Notes -

192.935(a)	Sat+	Sat	Concern	Unsat	N A X	N C
Notes – No measures implemented at this time.						
Public Awareness and Damage P	revent	ion -	ROW M	arkers	s, Pat	rols
Leakage Survey and Monitoring						
4. Placement of ROW Markers (detail) Are line markers (pd.RW.ROWMARKER.O) (detail)	arkers place	d and ma	intained as red	quired?		
192.707(a) (CGA Best Practices, v4.0, Practice 2-5; CGA Best Practices, v4.0, Practice 4-20)	Sat+	Sat X	Concern	Unsat	NA	N C
Notes						
5. Placement of ROW Markers (detail) Are line moipelines? (PD.RW.ROWMARKERABOVE.O) (detail)	arkers place	d and ma	intained as red	guired for al	bove groui	nd
192.707(c) (CGA Best Practices, v4.0, Practice 2-5; CGA Best Practices, v4.0, Practice 4-20)	Sat+	Sat X	Concern	Unsat	NA	N C
Notes						
5. ROW Conditions (detail) Are the ROW conditions a PD.RW.ROWCONDITION.O) (detail)	cceptable fo	r the type	of patrolling ι	ısed?		
192.705(a) (192.705(c))	Sat+	Sat X	Concern	Unsat	NA	N C
Notes						
				_		
Time-Dependent Threats - Exterr	ial Cor	rosio	n - Coa	tings		
12. Exposed Pipe Coating (detail) Is exposed burie (TD.COAT.EXPOSEINSPECT.O) (detail)	d pipe coatin	g inspect	ed to determin	e if it is det	eriorating	?
92.459	Sat+	Sat X	Concern	Unsat	NA	N C

Training and Qualification - Qualification of Personnel - Specific Requirements (O and M Construction)

6. Qualification of Welders (detail) Do welders dem (TQ.QUOMCONST.WELDER.O) (detail)	onstrate ad	lequate sk	ills and knowle	edge?		
192.227(a) (192.227(b); 192.229(a); 192.229(b); 192.229(c); 192.229(d); 192.805(h); 192.807(a); 192.328(a); 192.328(b))	Sat+	Sat	Concern	Unsat	N A X	NC
Notes - No construction or repair welding to observe						
9. Qualification of Nondestructive Testing Personal demonstrate adequate skills and knowledge? (TQ.QUOMCONST.N			o nondestruct	ive testing _l	personnel	
192.243(b)(2) (192.807(a); 192.328(a); 192.328(b))	Sat+	Sat	Concern	Unsat	N A X	NC
Notes – No construction or repair welding to observe						
Training and Qualification - Qualif	ficatio	n of l	Personr	nel - S	pecifi	C
Requirements						
5. Qualification of Personnel Tapping Pipelines taps demonstrate adequate skills and knowledge? (TQ.QU.HOTTA			e (detail) 🛭	o personne	el performi	ng hot
192.627 (192.805(h))	Sat+	Sat	Concern	Unsat	N A X	NC
Notes - No construction or repair welding to observe						
8. Qualification of Personnel who Oversee and (detail) Do individuals who oversee marking, trenching, and b (TQ.QU.EXCAVATE.O) (detail)						
192.805(b) (192.805(h); ADB-06-01; 192.801(a); 192.328(a); 192.328(c))	Sat+	Sat	Concern	Unsat	N A X	N C
Notes - No construction or repair welding to observe						
Training and Qualification - Traini	ina of	Perso	onnel			
						,
3. Emergency Response Training (detail) Do eme knowledge? (TQ.TR.TRAINING.O) (detail)	rgency resp	oonse pers	sonnei demons	strate adequ	Jate skills i	and

Sat+

Sat

Concern Unsat

192.615(b)(2) (192.805(b))

Notes - No emergency response to observe

NΑ

NC

Training and Qualification - OQ Protocol 9

192.801(a) (192.809(a))	Sat+	Sat	Concern	Unsat	N A X	N C
Notes – No construction or maintenance	to observe					
2. Qualification Status (detail) Versions the covered tasks. (TQ.PROT9.QUALI		the obser	ved covered to	asks are cui	rrently qu	alified to
92.801(a) (192.809(a))	Sat+	Sat	Concern	Unsat	N A X	N C
Notes – No construction or maintenance	to observe					
Abrasional Operations Condition	Decembries and Dece	tion (d	-1-11	.,		
B. Abnormal Operating Condition overed tasks are cognizant of the AOCs that						rming
					NA	
92.801(a) (192.809(a))	Sat+	Sat	Concern	Unsat	X	NC
Notes - No construction or maintenance	3	Sat	Concern	Unsat	X	NC
	3	Sat	Concern	Unsat	x	NC
Notes - No construction or maintenance I. Verification of Qualification (d	to observe etail) Verify the qualification	n records a	are current, an	nd ensure th	ne persona	n/
Notes - No construction or maintenance I. Verification of Qualification (didentification of all individuals performing coverage)	to observe etail) Verify the qualification	n records a	are current, an	nd ensure th	ne persona	n/
	to observe etail) Verify the qualification ered tasks are checked, prior to	n records a o task peri	are current, an formance. (TQ	nd ensure th	ne persona RIFYQUAL. N A	ol O) (deta
Notes - No construction or maintenance 1. Verification of Qualification (didentification of all individuals performing coverage) 92.801(a) (192.809(a))	to observe etail) Verify the qualification ered tasks are checked, prior to	n records a o task peri	are current, an formance. (TQ	nd ensure th	ne persona RIFYQUAL. N A	ol O) (deta
Notes - No construction or maintenance 1. Verification of Qualification (didentification of all individuals performing covers) 1. 92.801(a) (192.809(a)) 1. Notes - No construction or maintenance	etail) Verify the qualification ered tasks are checked, prior to Sat+	n records a o task pen Sat	are current, an formance. (TQ Concern	od ensure th .PROT9.VER	ne persona XIFYQUAL NA X	ol O) (deta
Notes - No construction or maintenance 1. Verification of Qualification (diametrication of all individuals performing coverage) 92.801(a) (192.809(a))	to observe etail) Verify the qualification ered tasks are checked, prior to Sat+ to observe es (detail) Have potential	n records a to task pen	are current, an formance. (TQ Concern	od ensure th .PROT9.VER	ne persona XIFYQUAL NA X	ol O) (deta NC
Notes - No construction or maintenance 1. Verification of Qualification (didentification of all individuals performing coverage) 92.801(a) (192.809(a)) Notes - No construction or maintenance 5. Program Inspection Deficienci	to observe etail) Verify the qualification ered tasks are checked, prior to Sat+ to observe es (detail) Have potential	n records a to task pen	are current, an formance. (TQ Concern	nd ensure th .PROT9.VER Unsat	ne persona XIFYQUAL NA X	ol O) (deta NC

Acceptable Use: Inspection documentation, including completed protocol forms, summary reports, executive summary reports, and enforcement documentation are for internal use only by federal or state pipeline safety regulators. Some inspection documentation may contain information which the operator considers to be confidential. In addition, supplemental inspection guidance and related documents in the file library are also for internal use only by federal or state pipeline safety regulators (with the exception of documents published in the federal register, such as advisory bulletins). Do not distribute or otherwise disclose such material outside of the state or federal pipeline regulatory organizations. Requests for such information from other government organizations (including, but not limited to, NTSB, GAO, IG, or Congressional Staff) should be referred to PHMSA Headquarters Management.

Page 9 of 9 Through Amdt. 192-116 August 2013